



San Luis Obispo Fire Department

Report for Incident 10-00651

Judith 1/26/17

Nature: Fire Structure
Location: FZ1

Address: 672 BRANCH
San Luis Obispo CA !

Offense Codes:

Received By: Steeb, C

How Received: 9

Agency: SLFD

Responding Firefighters:

Responsible Firefighter: Brady, Pat

Disposition: COM 02/19/10

When Reported: 20:25:22 02/18/10

Occurred Between: 20:25:16 02/18/10 and 20:25:22 02/18/10

Assigned To:
Status:

Detail:
Status Date: **/**/**

Date Assigned: **/**/**
Due Date: **/**/**

Alert Codes:

Circumstances

Responding Firefighters:

Unit :

Brady, Pat	T1
Farino, Robert	T1
Gatton, Chris	T1
Pratt, Jason	T1
Clinite, Mike	2
Callahan, Matt	2
GABRIELE, GEOVO	2
MacDonald, John	3
Nerdrum, J	3
Hicks, Gene	3
Hais, Ray	4
Veillette, R	4
PARKER, DAVID	4
Slate, Chris	BC2
CDF Operator	CDF
Maggio, Rodger	PRV20
Gonzalez, Steve	4
Barrett, Richar	4
Skove, Shayne	4

+

Narrative

Date/Name: Fri Feb 19 00:46:04 PST 2010 Pat Brady

Dispatched to: T-1, E-2, E-3, E-4, 3464 and Batt 2 responded to the report of a structure fire. Additionally a male ran up to station 1's engine room and reported a fire at Chile Peppers restaurant or possibly in a home near by.

Conditions found: Upon our arrival we found heavy smoke showing from what appeared to be the entire roof area of 672 Branch. Upon walking around visualizing sides A, B, D and a portion of C I found heavy smoke throughout and heavy fire behind the windows of side D.

Actions taken: Batt 2 assumed Chile command. FF Pratt pulled a preconnect and applied water through the windows on side D. E-3 layed in a supply line to T-1, E-2 had RIC. When RIC was in place FF Pratt and I attacked the fire from the front door on side A. Advancing through the front door was slow and difficult, hampered by a large amount of pack rat storage. Upon E-4's arrival they reported heavy fire venting from sides C and side D. Early into the fire Batt 2 pulled out T-1 personnel and declared the fire to be defensive only. At that point E-4 and E-3 deluged sides C and D with preconnects. T-1 advanced along side B and fought fire through the windows, heavy fire was venting from windows. Later E-2 relieved T-1 on side B. T-1 laddered the roof and cut a vent hole at the peak of the roof. The fire was knocked down and SIO FIST was called into investigate. 3464 with several PCF FFs assisted with overhaul. Fire Marshal Maggio assisted investigators and gathered information.

Additional information: The number of occupants and who the residences were was unclear with conflicting reports. The number ranged from one to five. A Mr. [REDACTED], reported to be the sole occupant. However, family members reported that a grandmother, two cousins and some others lived in the home. The property owner is West Home Enterprises.

Investigators suspended investigations to wait for better light in the morning. The chain of custody was maintained. Captain Bisson maintained security and watched for rekindle throughout the night. Investigation resumed at 0830.

Possible cause: Under investigation. See investigators report.

N