



PRR 238-17

city of san luis obispo
request for public records
(Return to City Clerk's Office)

DEC 08 2017

The California Public Records Act (Government Code 6250, et seq.) was enacted to ensure public access to public records. This form will enable us to accurately and efficiently fill your request. With the exception of certain State-mandated records, or records that exceed the standard size, copies are \$.40 per page (standard or legal size). DVDs of City Council or Planning Commission meetings are \$29 each.

NAME: Raymond Hanson
ADDRESS: 3960 S. Higuera #213
San Luis Obispo, CA 93401
PHONE: 704-8106

DATE OF REQUEST: 12/8/2017
E-MAIL: rhanson@sdrs.biz
FAX:

INFORMATION NEEDED: For each record, describe type, date, subject, title, etc. Please be very specific.

Please provide narrations and reports pertaining to the 10/24/2017 fire at 3001 Bahis Court in SLO.

YOUR REQUEST WILL BE PROCESSED IN COMPLIANCE WITH THE PUBLIC RECORDS ACT.

California Government Code Section 6253 (c). Each agency, upon a request for a copy of records, shall, within 10 days from receipt of the request, determine whether the request, in whole or in part, seeks copies of disclosable public records in the possession of the agency and shall promptly notify the person making the request of the determination and the reasons therefore. In unusual circumstances, the time limit prescribed in this section may be extended by written notice by the head of the agency or his or her designee to the person making the request, setting forth the reasons for the extension and the date on which a determination is expected to be dispatched. No notice shall specify a date that would result in an extension for more than 14 days.

If you need assistance with this request or wish to review the records on site, please call the City Clerk's Office in advance at 781-7100 to schedule an appointment. The City Clerk's Office is located at 990 Palm Street, San Luis Obispo, CA 93401. You may email your request to cityclerk@slocity.org.

FOR OFFICIAL USE ONLY

Forwarded to:
Date Completed:
Charge (if any):
Mailed: Picked up:
E-Mailed:

1 As used in this section, "unusual circumstances" means, but only to the extent reasonably necessary to the proper processing of the particular request: 1) The need to search for and collect the requested records from field facilities or other establishments that are separate from the office processing the request. 2) The need to search for, collect, and appropriately examine a voluminous amount of separate and distinct records which are demanded in a single request. 3) The need for consultation, which shall be conducted with all practicable speed, with another agency having substantial interest in the determination of the request or among two or more components of the agency having substantial subject matter interest therein.

San Luis Obispo Fire Department

Report for Incident 17-05374

Nature: Fire Structure
Location: FZ3

Address: 3001 BAHIA; GRID N-11
San Luis Obispo CA 93401

Offense Codes:

Received By: Owens, J **How Received:** 9 **Agency:** SLFD
Responding Firefighters:
Responsible Firefighter: MacDonald, John **Disposition:** ACT 10/24/17
When Reported: 11:17:40 10/24/17 **Occurred Between:** 11:17:37 10/24/17 and 11:17:40 10/24/17

Assigned To: **Detail:** **Date Assigned:** **/**/**
Status: **Status Date:** **/**/** **Due Date:** **/**/**

Alert Codes:

Circumstances

-FPL Fire Property Loss

Responding Firefighters:	Unit :
CDF Operator	CDF
Vasquez, Mark	2
King, John	2
Flatos, Alec	2
Callahan, Matt	T1
Farino, Robert	T1
Polkow, Matthew	T1
Renner, David	T1
Reiss, Devin	4
Nason, Billy	4
Child, R	4
Larson, Jody	3
Jeckell, Matt	3
Williams, J	3
MacDonald, John	BC4
Aggson, K	CHIEF2
AMBULANCE 1	A1
Maggio, Rodger	PRV20
Olson, Garret	CHIEF

Bisson, Bob	BC3
Hale, Gary	T2
Hoover, Nick	T2
Larsen, P	T2
Hais, Ray	BC2

Responsible Firefighter: MacDonald, John

Agency: SLFD

Received By: Owens, J

How Received: 9 911 Line

Clearance:

When Reported: 11:17:40 10/24/17

Disposition: ACT **Date:** 10/24/17

:

Occurred between: 11:17:37 10/24/17

Misc Entry:

and: 11:17:40 10/24/17

Modus Operandi:

Description :

Method :

Narrative

Date/Name: Wed Oct 25 15:35:34 PDT 2017 J. MacDonald

Dispatched to:

Above location for structure fire with reports of possible victim with smoke and fire seen. While en route to the incident based on the amount of smoke an fire seen while approaching the incident BC 4 called a working incident.

Conditions found: Single story single family residents approximately 2200 square feet stick frame construction with stucco exterior. Residents was fully involved with fire. Fire was coming from all windows on side A, B, and C. The vegetation in the front yard was also on fire. Exposures on side B and C were also being impacted by smoke and fire.

BC 4 established Alrita IC and declared the residents as fully involved. Initial strategy was defensive. Command post was established up hill on Alrita st. E2 arrived on scene and was assigned division Alpha. Division A was assigned fire attack on side A and B.

E3 arrived and was assigned water supply and fire attack on side C.

E4 arrived and was assigned water supply and fire attack with division A.

Truck 1 arrived and was assigned to assist with man power.

Chief 2 arrived and was assigned division C. Engine 3 was then assigned to work with division C.

Alrita IC then requested one additional ambulance and two additional engines.

One engine for city coverage and one to report to scene.

Alrita IC requested a city bus with AC for rehab.

Chief 1 arrived on scene and took IC. BC 4 was assigned operations.

After some fire was knocked down, Truck 1 was assigned primary search. After a short attempt at primary search the victim was located deceased near the kitchen. Truck 1 was unable to remove the victim due to increased fire activity. Truck 1 notified operations that they could no longer conduct the rest of the primary search because it was unsafe.

Defensive fire activity continued. A second alarm was called by IC. Arriving crews relieved first arriving crews as they filtered through rehab.

After knockdown of the fire, primary and secondary search, salvage, overhaul and body recovery began.

SLOCO corner arrived on scene and the crew from 3471 assisted the corner with body recovery.

Division A assisted the family with removal of multiple guns and guitars from the residents.

Investigation was turned over to FM Maggio.

After the fire was declared out, BC 4 took back IC and units were released. The scene was secured with exterior fencing from the Fence Factory and the building department posted the building.

Patrol 1 was assigned to the incident and stayed through the night to make sure there was not a rekindle.

BC 4 cleared.

City units at scene: Chief 1 and 2, BC4, BC2, BC3, T-1, T-2, E2, E3, E4, Patrol 1, FM Maggio, FF Gabrielle, Fire Prevention staff, SLOPD

mutual aid units: E64, E21, E3471, E62, Templton fire, Santa Margarita fire, Five Cities Fire, Morro Bay Fire.

Please see supplemental reports for specific duties per division.

Follow up:

BC 3 made contact with the family the next day.

Possible cause: See FM Maggio's report.

Notifications Building Division - Newsline

Supplement Name: Vasquez, Mark

Date/Name: 10/25/17 Captain Vasquez Engine 2

Conditions found: Upon arrival Engine 2 (E2) observed a working structure fire that was well established and had immediate exposure threats. E2 was the second in Engine company on scene as part of a First Alarm assignment. Upon passing Engine 3 (who stopped on the Charlie/Delta corner) E2 proceeded to the Alpha/Delta corner to attack the heavy fire that was rolling out of multiple windows and the open front door on the Alpha side. The fire volume that was releasing on the Alpha side had at least 30' flame lengths and was wind driven igniting trees and vegetation on the exterior of the structure.

Actions taken: Engine 2 (E2) personnel attacked the fire with the deck gun and then transitioned to 2 1/2" hose lines. E2 was assigned division Alpha and used transitional attack until a feasible interior attack was safe to conduct. An attempt was made by crews to advance interior for fire attack and a primary search. E2 Captain took FF Reiss and FF Renner to the roof to ventilate the structure in order to make interior conditions safer. Upon completing the ventilation task we exited the roof. Shortly after exiting the roof I observed smoke conditions changing to high pressure turbulent smoke and observed interior conditions worsening. I made the decision to contact IC and make a request to evacuate the building and change to a defensive strategy. All personnel were evacuated and a PAR was conducted with all personnel accounted for. Division Alpha continued with a defensive strategy until the mop up phase of the fire was achieved.

Mark Vasquez
Captain

Date/Name: Deputy Chief Aggson Chief 2

Conditions found: Upon arrival, found single family split level residence with heavy involvement on floor 1 with immediate exposure hazard to side charlie of the residence. C2 positioned across the street on side delta out of the hazard zone.

Actions taken: C2 moved to the charlie exposure to assist with hose deployment and assumed division charlie. E3, positioned on side delta, utilized deck gun operations to reset the exposing fire. Hand-lines were stretched and transitioned into both exposure protection and direct attack. E3/E4 FF assigned to check attic space of charlie exposure (1655 Alrita) with thermal imaging to confirm no extension into the structure. Upon arrival of truck 2, FC Hale assumed Div C and C2 moved to the CP to assist Alrita IC. C2 relieved BC4 as Ops while for rehab. During operational period, T1 was repositioned alpha side to complete elevated stream extinguishment and exterior crews on alpha transitioned into the structure for final extinguishment, investigation and body recovery. BC4 relieved C2 and Alrita IC directed C2 to take BC3 to EMS facility for possible heat exhaustion. C2 cleared Med-Stop and responded to SVMC to standby with E3 FC who was receiving TX. C2 briefed C1 at SVMC and was released from the incident.

Keith Aggson
Deputy Chief

Condition Found: T1 was the third apparatus at scene behind E2 and E3. T1

parked several houses below the incident and was instructed by BC4 to assist with water supply. Upon walking up to the fully involved structure, Engineers Farino and Polkow were immediately put on hose lines for exposure protection on side C. T1 Callahan and FF Renner pulled E3 supply line to the front of E3 and found a dry barrel hydrant already in service to E2. T1 notified E4 to lay a supply line forward from Flora/Alrita and connect to E3. FF Renner became available and went to assist Captain Vasquez. Engineer Farino became available and removed garage door with T1. No fire extension found in the garage. T1 then assigned to Interior Group through front door, side A. Victim found supine in the kitchen with legs toward the front hallway. Obvious 1144, victim left in place without being touched by fire personnel. Interior group continued suppression until change to defensive fire attack. Outside structure, PAR given. T1 drove up Alrita, and set up aerial above power lines on side D, and flowed water. T1 crew then repositioned T1 onto Bahia Ct. in front of side A. Morro Bay Truck crew took over pumping T1. T1 crew sent to rehab. During mop up phase T1 assigned salvage and overhaul, removed approximately 16 guitars in cases from the structure and placed on side walk across the street from side A.

Supplement Name: Reiss, Devin

Date/Name: Sat Oct 28 14:00:19 PDT 2017

E4 responded as part of a first alarm assignment. Arrived to find balance of first alarm assignment on scene of a single family home with heavy smoke and fire coming from side A and C with an immediate exposure threat (house) on side C.

Assigned to supply water to E3 and then report to Div A. Once on scene DC Aggson reassigned E4 to Div C for fire attack and exposure protection. Child and Reiss on fire attack and Nason assigned to Pump 3 for engineer duties. Progress made to protect the side C exposure- progress limited by hydrant water supply. E4 could only backup existing lines and could not add hose lines to attack.

Reiss and Child and reassigned back to Div A for interior attack and attempt to make progress on attic fire. Child made interior attack with Reiss and Callahan. Limited progress with heat and smoke. Child Assigned to Callahan by Reiss. Reiss, Vasquez and Renner vertical vent. Child found body inside front door and to the right- did not remove.

Rehab for Reiss and Child

Reiss and Child reposition E4 to supply water to E2 from top of Alrita. 4" supply to E2 pump.

E4 assigned to Div C to remove fence between fire and exposure homes and extinguish smoldering spots in structure.

E4 assigned to place E4 as primary pump for mop-up with foam. Child, Reiss and Nason moved hoses and foam for operation. Child moved to mop-up/Div A.

Rehab for Reiss, Child and Nason

E4 assigned clean-up. Reloaded hose on E4, E2 and E3. Recovered what gear we could on scene.

E4 released from scene